

**EAST Search History**

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S24	20576	219/121.\$.ccls.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2009/03/20 19:06
S25	246	S24 and ((fusing splic\$5 join\$5) with (fiber fibre))	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:06
S26	8	S25 and ((real adj2 time) with measur\$6)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:06
S27	15	S25 and ((attenuation loss) with measur\$6)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:06
S28	1606	385/95-98.cccls.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:06
S29	8	S28 and ((real adj2 time) with measur\$6)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:06
S30	164	S28 and ((attenuation loss) with measur\$6)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:06
S31	10	S30 and ((arrest check halt stall interrupt intermit postpone suspend stop) with (heating welding splicing))	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:06

S32	15	("5638476").URPN.	USPAT	OR	OFF	2009/03/20 19:06
S33	10	("6062743").URPN.	USPAT	OR	OFF	2009/03/20 19:06
S34	81	(attenuat\$ and (heat\$5 splic\$5 weld\$6) and (fiber fibre) and (control \$5 interrupt\$5 stop \$5 halt\$5 discontinu\$5 shut \$5)).clm.	US_PGPUB	OR	OFF	2009/03/20 19:06
S35	139	S26 S27 S29 S31 S32 S33 S34	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:06
S36	0	(11/317899).APP.	USPAT; USOOR	OR	OFF	2009/03/20 19:12
S37	5	("4948412"   "5009513"   "5638476"   "6230522"   "6294760").PN.	US_PGPUB; USPAT; USOOR	OR	OFF	2009/03/20 19:15
S38	1944	385/95-99.ccls.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:27
S39	1005	385/140.ccls.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:27
S40	28	S38 and S39	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:27
S41	25	S40 not (S35 S37)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:27
S42	2	("5638476"   "5897803").PN.	US_PGPUB; USPAT; EPO	OR	ON	2009/03/20 19:36

S43	119	("3825319"   "3960531"   "3981561"   "4049414"   "4054366"   "4142126"   "4257671"   "4261640"   "4313744"   "4378490"   "4516827"   "4529262"   "4557556"   "4557557"   "4591231"   "4639078"   "4644145"   "4645294"   "4692610"   "4695125"   "4702549"   "4728170"   "4747673"   "4749257"   "4787700"   "4878730"   "4881793"   "4884859"   "4893889"   "4904044"   "5031994"   "5037176"   "5066094"   "5142603"   "5285516"   "5398296"   "5572313"   "5588087"   "6062743").PN. OR ("4557556"   "4557557"   "5588087"   "5897803"   "6464410").URPN.	US_PGPUB; USPAT; USOOR	OR	OFF	2009/03/20 19:39
S44	97	S43 not (S35 S37 S41)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:40

S45	47	S44 and (S38 S39)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:40
S47	56	S38 and attenuat \$5.ti,ab,clm.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:49
S48	25	S47 not (S35 S37 S41 S45)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:49
S49	62	S39 and (fuse\$2 fusing splice\$4).ti, ab,clm.	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:51
S50	36	S49 not (S35 S37 S41 S45)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:52
S51	15	S50 and (off\$1set mis\$1align\$5)	US_PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2009/03/20 19:52
S52	3	(heat\$4 and loss and melt\$4 and fiber and measur \$4 and off\$1set). clm.	US_PGPUB	OR	ON	2009/03/20 20:12
S53	6	(heat\$4 and (loss attenuat\$4) and fiber and measur \$4 and off\$1set). clm.	US_PGPUB	OR	ON	2009/03/20 20:13
S54	3	S53 not S52	US_PGPUB	OR	ON	2009/03/20 20:13

3/21/09 7:57:42 AM

C:\Documents and Settings\ORojas1\My Documents\EAST Workspaces\10544256.wsp